


EXHIBIT 29

	INSPECTION REPORT	Report Date:	11 MARCH	Conclusion
		Inspection No.:	CT04130	Passed
		Revise No.:	CTS-HN02-R3	Page 8 of 25

POTOS ATTACHMENT

Carton view



Shipping mark on 2 wider sides view



Top side view




Shipping mark on 2 narrower sides view for S



Barcode check

Shipping mark on 2 narrower sides view for M

	INSPECTION REPORT	Report Date:	11 MARCH	Conclusion
		Inspection No.:	CT04130	Passed
		Revise No.:	CTS-HN02-R3	Page 9 of 25



Barcode check



Shipping mark on 2 narrower sides view for M



Barcode check




Open carton




3PLY



Color box view

	INSPECTION REPORT	Report Date:	11 MARCH	Conclusion
		Inspection No.:	CT04130	Passed
		Revise No.:	CTS-HN02-R3	Page 10 of 25



Color box view for S



Color box view for S



Color box view




Color box view for S



Color box view



Color box view

	INSPECTION REPORT	Report Date:	11 MARCH	Conclusion
		Inspection No.:	CT04130	Passed
		Revise No.:	CTS-HN02-R3	Page 12 of 25



Color box view for M



Color box view for M



Barcode check



Color box view for L



Color box view for L



Color box view for L